

BSV450B08 (base) HSV450B05 (handset) - Release candidate

Published Date: 01 June 2019



To install a new firmware version on a base station and/or handset, please follow the instructions provided in the [firmware update guide](#).



WARNING

IMPORTANT NOTES:

- after upgrading to version 450BXX the **rollback to version 410Bxx or previous is not possible**
- **please read carefully the [release notes](#) before upgrading, some major known issue are present**
- after the base upgrade to 450B08 also handsets must be upgraded to the version 450B05

MAJOR KNOWN ISSUES:

- DECT-632: Wrong SIP request URI in Record-Route (strict routing) scenario. **This issue is breaking compatibility with 3CX SBC** (and other SBCs that require strict routing)
- DECT-629: **No audio** after hold INVITE or reINVITE

Update via <http://dect.snom.com>

- Firmware update server address: <http://dect.snom.com>
- Required version: **450**
- Required branch: **08** (for the base M700 and M300)
- Required branch: **05** (for the handsets M25 M65 M85)

Binaries download

- [M700](#) SHA-256: 3bbaa35807d0245691d8712ba2a5e348f5acf33d4d09d3f4b9b49ed521193a90
- [M300](#) SHA-256: a101956a2d6dddfc862727a84fd9dc9ce7302ce0193473375154fc6e411fc8d5
- [M85](#) SHA-256: cc8f22654f2faf6f7dc4e14b0168545526e9343506657287d259e521cf766d14
- [M65](#) SHA-256: 6c07195c9c116d76076be0cf910ccb56e5b791b0f17d26a0cdbcbd0099c73d07
- [M25](#) SHA-256: ad97f4f9d9df40f7bf75494089682021cf849b72e31e8660d322ffa7af788740