

# BSV501B1 (base) HSV501B2 (handset) - Official Release

Published Date: 01 September 2020



To install a new firmware version on a base station and/or handset, please follow the instructions provided in the [firmware update guide](#).



## WARNING

- After upgrading to version **450BXX** or higher the rollback to version **410BXX** or previous is **not possible**.
- After upgrading to version **500BXX** or higher you need to update also any **M5** Repeater you would like to use at least to **480B5**.
- please read the [release notes](#) carefully before upgrading

## Update via <http://dect.snom.com>

- Firmware update server address: <http://dect.snom.com>
- Required version: **501**
- Required branch: **01** (for the bases M900, M700 and M300)
- Required branch: **02** (for the handsets M25, M65, M70, M80, M85, M90)

## Binaries download

- **M900** SHA-256: 812b44a8fa3f598dcb6aeadbf1d78e5b9295268a40b00805213f5a40663aa33a
- **M700** SHA-256: f838c3a9d31a602ae202ffcf553c868d965093bb90bf0b6439368f52d80a83ca
- **M300** SHA-256: a45d55749b2f9ea181f2a5d73432121792f75fb3a19d841e6a67321006800a9b
- **M90** SHA-256: 3ae29b15ad68293170f68aae742b56a004b6317f029d2fb2fe32c521bfd46ece
- **M85** SHA-256: 632ea210b76fa603c902419418676589246c6516a06737aee63a986624dbe670
- **M80** SHA-256: 64015782c33006a89273f2e60ce44ee2cdeb62e15f610d13cda7a08c96685963
- **M70** SHA-256: 57bad5536b88e9b81c8cf61fe9782ded16a1ccef6aaa785f6d465c7963ea0c5e
- **M65** SHA-256: bbafa72777c99af1d7ba647c472e6b550e1b441fdc25a565ddea1b5cbb676ce7
- **M25** SHA-256: 798ae41c9caa8a588766f2c072c23f68bc749c9c22d487e451a442b850b9e91f